Date:

Thursday, 09/04/2009 7:02:21 AM

User:

Linda Lacelle

## **Process Sheet**

Customer

: CC-DAR01 Dart Aerospace Ltd.

Job Number

: 47098

**Estimate Number** 

: 10804

P.O. Number

This Issue

: 09/04/2009

: NC

: //

: 00015

Type

S.O. No. :

· SMALL /MED FAB

Part Number

**Drawing Name** 

: REWORK20 : R09-041

: D2562 / 2565

**Drawing Number Project Number** 

**Drawing Revision** 

Material

**Due Date** : 15/04/2009 Qty:

14 Um:

Each

Checked & Approved By

Prsht Rev.

First Issue

Written By

**Previous Run** 

Comment

**Additional Product** 

Job Number:



Seq. #:

Machine Or Operation:

Description:

QC5 1.0

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

The following have been inspected, in good condition, and to be returned to stock:

2x D2562-001 B42101

2x D2565-101 B41892

2x D2565-103 B41893

2x D2565-105 B41894

2x D2565-107 B41895 2x D2565-109 B42102

2x D2565-111 B41896

2.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Restock the obove items using the original batch # to the correct locations.

Make adjustment in ACCPAC for the qty's: See Linda or Mel



3.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



u 9,04.15